



Subject: Cylinder head

Affected engine models: All engines models

L 2000 DA
L 2400 EB

Background information: Leakage between cylinder and cylinder head.

Priority: None; measures will be taken as required; the modification will be included in the series.

Compliance: The cylinder heads are now cast from an aluminium alloy which has greater thermal strength characteristics. In addition, reinforcing sleeves are installed to improve the structural strength.

Remarks: This document has been translated to the best of our knowledge. In case of doubt however only the German original shall be considered authoritative

The german original of this Technical Bulletin has been authorized by the german aviation authority (LBA) on August 08, 1995

Bearb.: Stolinski

Replaces Edition from:

Page: 1

Gepr.: 



Edition: 30.03.95

of 1 Pages